Richmond Refinery LPS Alert - Safety

Routine Maintenance Contractor Hand Injury





LI Number: 24959

Location:

Routine Maintenance Richmond Refinery

Contact Information:

John Torres CTN 242-1287 JTLD@chevron.com

INJURY REENACTMENT



Toolbox lid was propped up for this reenactment

Incident Description:

On October 31, 2011 at approximately 1:00 p.m., a worker sustained a hand injury. The tip of the ring finger of his right hand was pinched by a pickup truck toolbox lid when he and another worker attempted to close the lid. The worker was not wearing gloves and the lid-lifting pistons were not functional.

Immediate Actions Taken:

- 1) Chevron Fire Department treated the injury in the field.
- 2) The employee was taken to an off-site facility for follow-up care.
- 3) An incident investigation was initiated.

Considerations:

- Do you recognize the potential risks of a task by doing a thorough LPSA, identifying pinch points and/or the line of fire?
- 2) Do you have the correct Personal Protective Equipment for the task?
- 3) Should Stop Work Authority have been used or considered in this situation?



Always remember to do your LPSA – because we care about you!

This document is intended for company workforce only. Nothing herein should be construed as a legal determination of causation or responsibility. The company makes no representations or warranties, express or implied, about the thoroughness, accuracy, or suitability of use by others of any of the information containined herein.